

Technical Bulletin

Model
911C4

Group
3

Subject: Front Wheel Drive Disconnecting

Part Identifier
3903

Number
9002

ATTENTION: Service Manager/Service Technician

Model Affected: 911 Carrera 4

Concern: Driving 911 Carrera 4 with Front Wheel Drive Disconnecting.

WARNING: Driving or testing a 911 Carrera 4 with the Front Wheel Drive disconnected will result in damage to the interaxle lock system.

DO NOT operate the vehicle in this manner for any purpose including road or dynamometer testing.

PORSCHE CARS NORTH AMERICA, INC.

Dealership _____	Service manager _____	Shop foreman _____	Service technician _____	_____	_____	_____
Distribution _____	Asst. manager _____	Warranty admin. _____	Service technician _____	_____	_____	_____
Routing _____						

©1990 Porsche Cars
North America, Inc.
All Rights Reserved
Technical Support
Department



SERVICE

Page 1 of 1
March 23, 1990