

Technical Bulletin

Model
911 C2/C4
928S/S4/GT

Group
4

Subject: Caster Adjustment Values

Part Identifier
4485

Number
9201

ATTENTION: Service Manager/Service Technician

Models Affected: 911 Carrera 2 and 911 Carrera 4 all model years
928S, 928S4, 928 GT from model year '86 (G)

Concern: Revised caster adjustment values.

Service Information: 911 Carrera 2 and
911 Carrera 4

The specified caster adjustment values and tolerances changed in production. The new value of

$$4^{\circ} 25' \begin{matrix} +15' \\ -30' \end{matrix}$$

should be applied to all 911 C2/C4 of all model years. The maximum difference between left and right remains 15'.

Please update your 911 Carrera 2/4 Workshop Manual, Volume IV, page 44-02.


928S, 928S4 and 928 GT

The specified caster adjustment values and tolerances changed in production. The new value of

$$4^{\circ} + 1^{\circ}$$

should be applied to all 928 models from model year 1986 (G). The maximum difference between left and right remains 20'.

Please update your 928 Workshop Manual Volume IV, page 44-05.



PORSCHE CARS NORTH AMERICA INC

